



1/8




(PRIOR ART)

FIG. 1















FIG. 15






FIG. 17




FIG. 18








FIG. 19









۵

PLASMA SPRAYING FOR JOINING SILICON PARTS 3816.10

6/8









FIG. 24







8/8

